

DATE 0630Z 20 FEB 65

S E C R E T

1	9
2	10
3	11
4	12
5	13
6	14
7	15
8	16

TO : DIRECTOR

FROM [REDACTED] 25X1A

ACTION:

INFO :

TOR 0708Z 20 FEB 65.

PRIORITY

IN 73004

25X1A

TO

PRIORITY [REDACTED]

INFO [REDACTED]

GITE

[REDACTED] 7700

25X1A

25X1A

A. C0450

B. FAIR

C. NO MAJOR PROCESSING TROUBLES ENCOUNTERED. SOME
PROCESSING STREAKS AND PIN HOLES NOTED.

CAMERA STATIC ON 9-R BURSTING ALONG BOTH EDGES
FROM HEAD TO TAIL, APPROX 1 INCH IN FROM EDGES.
MINUS DENSITY MARKS ON 9-L, 2 AND 3/4 INCHES IN
FROM THE CLOCK EDGE, AND REPEATING EVERY 1 AND 3/4 INCHES.
PLUS DENSITY LINE ON 9-R-PARTS, 1-2-3 ONLY, AND IS
3 AND 3/8 INCHES IN FROM THE OUTBOARD EDGE.

METERING TROUBLE ON 9-L-THE FIRST TWO FRAMES ARE
OVERLAPPED.

EDD [REDACTED]
RS [REDACTED]
RP [REDACTED]
KB [REDACTED]
WC [REDACTED]
DB [REDACTED] G3
NM [REDACTED]
PA [REDACTED]
RG [REDACTED]

END OF MSG

GROUP 1
EXCLUDED FROM AUTO-